

PROGRAM ADMINISTRATOR DEPARTMENT ALECP INTERTEK 3933 U.S. ROUTE 11 CORTLAND, NY 13045-0950

JAQUITH INDUSTRIES, INC. 600 East Brighton Ave Syracuse, NY 13205 ORIGINAL ISSUE DATE: August 10, 2016

Recertification due: <u>December 2019</u>

An Activity Sponsored and Administered by Intertek

AIRPORT LIGHTING EQUIPMENT CERTIFICATION PROGRAM

CERTIFICATE OF CONFORMANCE

The product described below is hereby approved for listing in the next issue of the Federal Aviation Administration (FAA) Advisory Circular (AC) 150/5345-53, Appendix 3 Addendum "Airport Lighting Equipment Certification Program. The approval is based on successful completion of tests in accordance with the specifications listed in, and the requirements for approval described in the Advisory Circular, and the reporting to the Program Administrator the results of such tests, accompanied by related documents by an Intertek recognized testing laboratory. This Certificate is only confirmable in conjunction with equipment being listed in AC 150/5345-53, Appendix 3, Addendum, as currently published by the FAA. The certification is not valid for a product modified with non-OEM replacement parts or non-production components.

L-867 – Light Base, Non-load Bearing L-868 – Light Base, Load Bearing (AC 150/5345-42H)							
				Manufacturer's Catalog Number			
Mfg	Type	Size	Class	Base	Ext	Cover Plate	Spacer Rings
Jaquith Ind.	L-867 L-867 L-867 L-867 L-867	B B D D E	1B 1B 1B 1B	ACS20XXXXXXXXXXPCC ACS21XXXXXXXXXX ACS63XXXXXXXXXX ACS60XXXXXXXXXXPCC	AES2XXXX AE6SXXXX	AKS10XXXX AKS20XXXX AKS70XXXX	ATS2006XX ATS6003XX ATS7003XX

- 1. This Equipment requires continuing validation in accordance with the requirements of AC 150/5345-53, and the Intertek Airport Lighting Equipment Certification Program.
- 2. Product tested and Report issued by: Jaquith Industries; Intertek

(A) Report No: G102059108W42015; 102122549CRT-001; 100311667W812; 100514345W

(B) Date of Report: 8/2015; 7/2015; 8/2012; 12/2011

NOTE: PLEASE REVIEW, AND ADVISE ADMINISTRATOR AT INTERTEK IMMEDIATELY IF DATA, AS SHOWN, NEED TO BE CORRECTED.

Jeremy N. Downs, P.E., Program Administrator

Date: August 10, 2016

Approved for Certification by: